

Parker Precision Guitars

Work Order | Setup, Corrective Work, and Final QC

MOCK

JOB ID MOCK-TELE-001	CUSTOMER Mock Customer	RECEIVED 8/28/2026	COMPLETED 8/30/2026
MFG Fender	MODEL Telecaster	SERIAL MX23091452	TUNING Standard
PHONE	EMAIL	TECHNICIAN Parker Precision Guitars	STATUS Ready for Pickup

Customer Request

Set up for clean standard tuning, smooth bends, stable tuning, and balanced Telecaster pickup output. Check saddle travel, tuner feel, nut/string path, and electronics while the instrument is on the bench.

Setup Specifications

Component	Incoming	Outgoing	Method	Check	Check In	Check Out	Notes
Neck relief	0.012 in	0.010 in	Measured at playing position	Pass	8/28	8/30	Set.
Action Low E @ 12th fret	6/64 in	5/64 in	4R 6 in ruler	Pass	8/28	8/30	Set after saddle correction.
Action High e @ 12th fret	4/64 in	4/64 in	4R 6 in ruler	Pass	8/28	8/30	Set.
Nut slot Low E	Within SOP feel check	No nut-slot work performed	2nd fret; feel 1st-fret gap	Pass	8/28	8/30	About 0.003 in target.
Nut slot High e	Within SOP feel check	No nut-slot work performed	2nd fret; feel 1st-fret gap	Pass	8/28	8/30	About 0.003 in target.
Pickup height - neck bass	8/64 in	7/64 in	4R 6 in ruler	Pass	8/28	8/30	Balanced.
Pickup height - neck treble	7/64 in	6/64 in	4R 6 in ruler	Pass	8/28	8/30	Balanced.
Pickup height - bridge bass	7/64 in	6/64 in	4R 6 in ruler	Pass	8/28	8/30	Balanced.
Pickup height - bridge treble	5/64 in	4/64 in	4R 6 in ruler	Pass	8/28	8/30	Balanced.
Intonation	12th fret: Low E +9 cents, A +4, D +3, G -2, B +1, high e +6	12th fret: Low E +2 cents, A +1, D 0, G -1, B 0, high e +1	Analog tuner; cents	Adj.	8/28	8/30	Final cents check passed.
Electronics	Output present; light contact noise	Controls clean; jack secure	Functional test	Cleaned	8/28	8/30	Cleaned.
Frets / neck	Frets seated; light oxidation	Polished; no high-fret issue found	Visual/play test	Pass	8/28	8/30	Polished.

Setup Specifications, Continued

Component	Incoming	Outgoing	Method	Check	Check In	Check Out	Notes
Bridge / trem	Low E saddle bottomed early	Travel restored	Bench inspection	Fixed	8/28	8/30	Rechecked.
Nut / string path	G string binding at tuner post hole	String returns to pitch	Bend and retune test	Fixed	8/28	8/30	Stable.

Work Performed

000-001 - Full Meal Deal Source: Package		
Requested / finding: Complete setup for standard tuning, lighter action, tuning stability, clean electronics, and balanced output.		
Work performed: Adjusted relief, set action to 5/64 in Low E and 4/64 in high e at the 12th fret, set pickup heights, cleaned contact noise, polished frets, and completed play-test.		
Labor	Setup labor and final play-test	\$90.00
Materials	String set and shop supplies	\$14.00
Section total		\$104.00

500-200 - Bridge saddle slot - cut / lower Source: Corrective		
Requested / finding: Low E saddle reached the floor of its adjustment range before the setup target.		
Work performed: Corrected the saddle contact point, restored adjustment travel, and rechecked action and intonation.		
Labor	Corrective saddle work	\$30.00
Materials	No charge	\$0.00
Section total		\$30.00

Parker Precision Guitars

Work Order | MOCK-TELE-001

MOCK

700-200 - Tuner post / hole - deburr, grind, polish Source: Corrective		
Requested / finding: G string caught at the tuner post hole during bends and retuning.		
Work performed: Deburred and polished the string contact area, restrung, stretched strings, and verified return to pitch.		
Labor	Tuner post correction and recheck	\$20.00
Materials	No charge	\$0.00
Section total		\$20.00

Final QC

Tuning stability	Pass	8/30
Open strings and first-position chords	Pass	8/30
Controls and output jack	Pass	8/30
Final play-test	Pass	8/30

Completion Note

Setup completed, corrective items verified, and the instrument passed final play-test in standard tuning.

Labor	\$140.00
Materials	\$14.00
Total	\$154.00

Technician signature

Customer pickup confirmation

Thank you. This mock work-order example shows how Parker Precision Guitars documents measurements and completed work. It is not a customer record or a price quote.